ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	10	Dodda Bommasandra
Street ID	**Street Name**	**Significant Landmark**
W0105, W0022, W0054, W0025	NA	surya bakery road Doddabommasandra
Segment No.	**Total Length (m)**	
10/C-W0105/S013213	161.98	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	161.98	77.555400	13.067725	77.556480	13.067230	DEAD END	W0054

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Improvements to Roads, Drain and Covering slab at surya bakery road in ward no 10 (Doddabommasandra) Vidyaranayapura Sub-Division Yelahanka zone	1000000	2014
Year	**Type of Work**	**Other Work Type**
2014 - 2015	Others	Drain and Covering slab
Tender	**Work Details**	**Job No. / Work Code**
Tender	Improvements to Roads, Drain and Covering slab at surya bakery road in ward no 10 (Doddabommasandra) Vidyaranayapura Sub-Division Yelahanka zone	010-15-000026
Work Order No.	**Work Order Date**	**Period of Extention**
EE/BTP/BBMP/E-PMT/299/2014-15	06/02/2015	60 DAYS
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
06/02/2015	05/02/2016	Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
SHARANAPPA.M.PRABHANNAVAR		0.00
Phone No.	**E-Mail ID**	

9448961045

Field Inspection Details

Number of Trees	Any Other Information	Name
17		MADHAVA RAO
Date of Inspection	**Remarks**	
21/06/2016	completed	

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.

Zone: YELAHANKA **Ward No:** 10 **Ward Name:** Dodda Bommasandra **Street ID:** W0105, W0022, W0054, W0025

Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	PARAMESHWARAIAH	21/06/2016	21/07/2016	COMPLETED
SE	VASU K M	21/06/2016	21/07/2016	COMPLETED
EE	VASU K M	21/06/2016	21/07/2016	COMPLETED
AEE	MAHADEV.B.A	21/06/2016	21/07/2016	COMPLETED
AE	MADHAVA RAO	21/06/2016	21/07/2016	COMPLETED
AE	MADHAVA RAO	21/06/2016	21/07/2016	COMPLETED

Zone: YELAHANKA **Ward No:** 10 **Ward Name:** Dodda Bommasandra **Street ID:** W0105, W0022, W0054, W0025